FIRE RISK ASSESSMENT - CHAPEL HALL

HAZARD	RISK	PREVENTATIVE	RISK RATING
		MEASURES	
Electricity	Electrical fault	Fixed wiring tested	
		every 5 years	LOW
		Portable appliances	LOW
		tested every two years	
		Any faults reported to	LOW
		Trustees as soon as	
		possible and item	
		removed from use	
Combustible materials	Accidental ignition	Combustible materials	
	, recorder rear regimene	stored securely	LOW
		,	
		Waste bins emptied at	LOW
		end of session	
		Good housekeeping	LOW
Emergency evacuation	Inability to exit	Fire exits clearly	
	building	signed and kept clear	LOW
		at all times	
		For any and it shall a	1014
		Emergency lighting available and	LOW
		maintained, tested	
		every three months	
Fire fighting	Unable to extinguish	Appropriate fire	
THE HEIGHTINE	fire	extinguishers available	LOW
	111 C	at exits	2011
		Fire blanket available	LOW
		in kitchen	
		Extinguishers tested	LOW
		annually	
Arson	Unauthorised person	Building secured when	1014
	entering property	not in use	LOW
		No combustible	LOW
		materials stored	2011
		outside building	
		2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	
		Refuse bins situated	LOW
		away from building	

FIRE RISK ASSESSMENT – TRUSTEES STORE

HAZARD	RISK	PREVENTATIVE MEASURES	RISK RATING
Paper/card storage	Ignition	All documents stored in metal filing cabinets	LOW
		No sources of ignition in store room	LOW
		Good housekeeping	LOW
		Store room locked when not in use	LOW
		Authorised access only	LOW
		Electrical wiring checked every 5 years	LOW

01.03.2023

Review Annually