CC	HC	Road			Community Council						TEC Services					Signoff	
Ref	Ref	No.	Starts	Ends	Issue	Description of fault	Date reported	Photographs	Priority	Latest Date - Comment	Response	Priority	Date work scheduled	Date complete	Latest Date - Comment	TEC	CC
1		**Unclassified** - The main Braeintra road i.e. From the A890 down through Braeintra	Just uphill from **Soluis mu Thuath**	At the bridge across the burn	Water floods the road and freezes	Ditches and gullies under driveways are blocked uphill from Soluis mu Thuath causing water to run onto the road. In addition the drain hole on the bridge is blocked leaving a large amount of water in a pool on the road.	2010	Sent to George 23 May 2012	1	23 May 2012 - Potentially lethal when temperatures drop below zero							
2	434898	**Unclassified** - The coast road that runs from Plockton through Duncraig and Craig to Achmore	Traveling from Plockton to Achmore, where the new tarmac surface starts after turning left at the T junction for Duncraig	Approximately 200 yards from the start of the new tarmac just past the third passing place	If cars leave the tarmac they will get stuck as they will be grounded on their chasis. This is particularly a problem if reversing to allow another car to pass in the dark	Where the new tarmac has been laid there is a drop of up to 330 mm to the verge in places	03/10/2012	I think is fairly clear where the problem is, but let me know if you would like me to take some pictures to help identify the location		3 October 2012 - Reported by Phil Game not life threatening but would cause a major problem if someone did become stuck							