


ANNEX 1

PIRBRIGHT FLOOD FORUM ACTION PLAN
Lord Pirbright's Hall

11 February 2022 at 11am

ACTION REQUIRED	BY WHOM	STATUS/UPDATE
<p><u>Action Point 1</u></p> <p>Mill Lane Temporary bunds are to be checked to ensure they are still doing their job. (Close to Brambles).</p> <p><u>(photo unavailable)</u></p>	<p>Brent Shirley</p>	<p>Unknown location. No recent reports. Check location of bunds with Brent Shirley and assess.</p>
<p><u>Action Point 2</u></p> <p>Mill Lane – grips in banks alongside lane become blocked so that rain water cannot run off the road into stream.</p>	<p>Patrick Giles</p>	<p>Initially resolved. Some grips blocked each year and need clearance.</p>
<p><u>Action Point 3</u></p> <p>A324, Aldershot Road – flooding near the Royal Oak Work has been attempted but proved problematic due to pipes leading to a soakaway. Consent required.</p> 	<p>Patrick Giles</p>	<p>Update required please, no information on status.</p>

Action Point 4

Stanley Hill, B3405

needs excavation



Patrick Giles

Update required please, no information on status.

Action Point 5

School Lane

Railings at Causeway Bridge to be fixed



SCC Structures

Status of railings unknown but appear damaged. To be checked and reported to next meeting.

Action Point 6

A324 Connaught Road, flooding by bus stop on the border of Pirbright and Brookwood. Problem to be looked at and Woking to be involved if required. There is a problem with the location because of Pirbright Arch traffic lights would need to be switched off. Pipe from garage to canal has been cleaned, system on south side needs jetting to be arranged with Woking team



Patrick Giles

Update required please, some concern over flooding continuing on corner and under bridge. Report to next meeting.

<p><u>Action Point 7</u> Fox Corner Wildlife area – pipe to Hodge Brook is too small and installation of a new larger pipe is now required. A survey was undertaken by Geoff Fowler.</p> 	<p>Helen Barnsley / Brent Shirley</p>	<p>Unknown status. HB to review and report to next meeting.</p>
<p><u>Action Point 8</u> Cemetery Pales & Chapel Lane – flooding near Mowbray and Limnau. Some jetting has already been done, should be added to work list for further work. Grips have been cut opposite the houses to allow surface water to drain rain from the road into the ditch.</p> 	<p>Steve F/Patrick Giles to monitor</p>	<p>This continues to be an issue. Regular flooding of the footway at the entrance to Chapel Lane and further west across the width of the road before entering the Green. Blocked (silted) drains and gips.</p>
<p><u>Action Point 9</u> Gapemouth Road, flooding under the tunnel on the bend towards Pirbright. A gully is needed to drain the water, but Network Rail is asking for payment. A temp solution has been put in place.</p> 	<p>Patrick Giles</p>	<p>Improvements previously made have resolved the worst issues but needs monitoring each year.</p>

Action Point 10 – new Action

Sites 1 & 2 on Gole Road, widening of watercourse by landowner, causing potential flooding to School Lane at Causeway bridge. Installation of water supply by Thames Water and toilets on site with raw sewerage going into ditch ultimately leading to the Hoe at Fox Corner.



Current flooding south of the Gole Road site across School Lane at Causeway Bridge when flash floods occur

Thames Water
Environment Agency

Encourage reporting of future incidents via Thames Water website for sewage and Environment Agency if pollution incident. Report flooding of School Lane via SCC. There remains some concern over flooding of the road in heavy rainfall periods.

Property Level Protection Scheme.
This was never published to Pirbright residents

Advice PPC if any further initiatives taken and maintain defence works and grips to help alleviate issue.