## **Broadband Steering Group**

Minutes of the Meeting held on the 10<sup>th</sup> November 2021 @ 7:30 pm by Zoom

# 1 Present and Apologies

Present: Phil Game, Mary MacBeth, Kath Smith, Neil MacRae

## 2 Approve and adopt previous minutes

The previous minutes for October, were proposed by Neil, seconded by Kath Copies of previous minutes are on our website at:-

http://www.stromeferry-and-achmore.co.uk/index.asp?pageid=433827

# 3 Chairman's report

A considerable amount of time has been spent working on the AGM documents, NJP rebates and accounts; this has impacted the time available for other tasks.

#### 3.1 Bandwidth

The Lochcarron Shinty Club have responded positively to our approach and the next step will be to visit and discuss in detail the location of our equipment. **Action: Mary** 

#### 3.2 False RADAR

Our false RADAR software has been enhanced to produce an email summary; this is currently under test and will be set up to be run automatically overnight. **Action: Phil** 

### 3.3 Subscribers

Live subscribers	- 53
Waiting for installations / activation	- 1
Waiting for subscriber's confirmation of details	- 0
Pending installations	- 5
Waiting for installations	- 12
Leavers since the last minutes	- 0
New joiners since the last minutes	- 0
Total	- 71

As we will need to return to North Strome to continue work on the Strome Ferry relay we will take the opportunity to complete the newly requested installations in North Strome and Leacanashie. **Action: Phil** 

We have had requests for connections in Lochcarron and Strathcarron; once our existing commitments have been met we will see if these are feasible and schedule the work. **Action: Phil** 

We have had an enquiry for a new connection and have been told by the subscriber that they do not have line of sight. We may review this when all other subscribers have been connected. **Action: Phil** 

See section 8.7 for more details on implementations

# 4 Secretary's report

## 4.1 Risk register

No progress this month.

### 4.2 Long term support plan

Software to automate the cloning of devices - this software is currently being updated to work with the newly purchased "AC Gen 2" units so that they can be used in Strome Ferry. This will take a little long than normal as the software has to be amended to cater for alternate frequency widths which will affect all units not just the new Gen2s. Action: Phil

## 4.3 Access to the bank account

No progress this month. Action: All

## 4.4 Electricity account

The finance spreadsheets have been updated with the predicted usage costs. Completed

# 5 Finance Director's Report

## 5.1 Monthly Statistics

#### **Revenue for October**

**Brought forward** 

Balance £388.92

 Creditors
 £9,802.78

 Debtors
 £7,957.29

Net £1,845.49

Bank balance £9,427.16

This month

Income £547.50 Expenditure £369.42

P&L £178.08

 Creditors
 £137.00

 Debtors
 £435.00

Net -£298.00

Adjusted P&L -£119.92

Carried forward

Balance **£567.00** 

 Creditors
 £9,939.78

 Debtors
 £8,392.29

Net £1,547.49

Bank balance £9,307.24

### 5.2 Last year's surplus

The third batch of subscribers to receive cheques refunding a portion of the New Joiner's Premium has been agreed and will be dispatched within the next few days. Action: Kath, Neil, Phil & Mary

There are still a few subscribers with anomalies on their accounts cheques will be issued as soon as these have been resolved. **Action: Subscribers** 

### 5.3 Outstanding Expenses Claims

All expense claims are up to date.

### 5.4 Next year's tariff

The total number of gigabytes sold was 14,550. The break even tariff for 3 fibre lines is 130 GB per £1 and for 4 fibre lines 105 GB per £1.

## 5.5 Outstanding subscribers' debt

Again there are too many anomalies this month to provide a meaningful figure.

#### 5.6 Housekeeping

Work continues to automate the reconciliation of payments; priority will be given to Zen & Plusnet. Action: Phil

### 5.7 Payments for installations of subscriber's equipment

All payments are up to date.

## 6 Internal auditor's report

It was agreed we would prepare a synopsis of our current practises, needs and areas of weakness to assist ourselves and the auditor. No progress this month. **Action: Phil** 

## 6.1 Assets, bf, acquired, relinquished / written off, cf

No progress this month.

### 6.2 Liabilities

No progress this month.

## 6.3 Description of the Audit Trail

No progress this month.

## 7 Customer Relations

### 7.1 Production Environment

We are still seeing sporadic problems with the Achmore access point. Action: Phil

One subscriber reported poor performance in Braeintra - this is down to obstructions in the line of sight of the subscriber's antenna. **Action: Subscriber** 

Drop outs in Craig - we have not recorded any drop outs for several months; however we will continue to monitor the link. Action: Phil

We continue to hold the Lochcarron gateway in reserve should there be a need to increase capacity.

The MikroTik server ("The Dude") is having its database rebuilt - the newly installed equipment has been set up but there is still more work to do. Action: Phil

Phil is part way through a document to list the options for automatic recovery of failures and loss of capacity. No progress this month. **Action: Phil** 

The damaged Strome Low relay dish that connects to Achmore High will be recovered when we next schedule work on Creag Mhaol. Action: Phil

The Creag Mhaol dish that connects to Ardaneaskan West that was replaced after storm damage is showing some slight dips in signal strength. This is probably due to a damaged housing, the housing will be replaced when we next schedule work on Creag Mhaol. Action: Phil

An unplanned power cut caused problems with the link from the Glen to Creag Mhaol. The units' automatic reboot recovery had to be disabled. Once the current round of power outages is complete we will restore the automatic reboot recovery feature. **Action: Phil** 

A series of power cuts (some planned, some not planned) caused interruptions to the service. Manual intervention was required to reset some units because automatic recovery of units after a power cut has been temporarily disabled whilst false RADAR events are being investigated. **Action: Phil** 

7.1.1 Usage quotas

The monthly total for October was 8.2 TB (new record). The daily average was 266 GB (new record), with a peak usage of 411 GB (new record) on Sunday 24<sup>th</sup>.

CMNet peaks since operations started; highest average daily usage 266 GB, highest single days usage - 411 GB, highest monthly usage - 8.2 TB.

Four subscribers exceeded their quota and have had their contracts amended accordingly.

7.1.2 Possible virus infection

No new instances of the Ubiquiti virus were detected; we will continue to run scans. Action: Phil

7.1.3 Installation of equipment

7.1.3.1 Achmore

Nothing to report

7.1.3.2 Ardaneaskan East

Nothing to report

7.1.3.3 Ardaneaskan West

Nothing to report

7.1.3.4 *Ardnarff* 

Nothing to report

7.1.3.5 Braeintra

We will configure and install backup units for the Achmore side relays as soon as time permits. Action: Phil.

7.1.3.6 *Craig* 

We are investigating a report of drop outs. We will review the situation when we have more experience of low level links over water or other options become available. **Action: Phil** 

7.1.3.7 North Strome

Nothing to report

7.1.3.8 Strome Ferry

Replacing the unit in North Strome has been hampered by a month of rain. Action: Phil

7.1.3.9 Other installations

Nothing to report

7.1.4 Customer Contracts

We will check that all changes to customer contracts and charges are now correct. Action: Phil

## 7.2 Changes for next month

## 7.2.1 Additional Management tools / reports

Management Reporting Software upgrades. No progress this month. Action: Phil

Software to check the configuration of equipment - this is being upgraded to increase the automation when configuring new devices and simplify the configuration of backup units. **Action: Phil** 

## 7.2.2 Potential personal safety issue

The new naming standard has been used for all the new installations. Action: Phil

## 7.2.3 Additional equipment for subscribers

Ardaneaskan - One site has requested a scan / trial for whole house Wi-Fi.

### 7.3 Volume trial

#### 7.3.1 Review of the trial

No progress this month. Action: Phil

## 7.4 Terms of Reference

Deferred

## 7.5 Problem reporting procedure

A trial WhatsApp group has been set up by Mary - testing is continuing amongst directors. Action: All

# 8 General topics

### 8.1 Documentation

### 8.1.1 Creag Mhaol

We have received a draft lease agreement from our solicitors; we have yet to go through this in detail. We will need to reconfirm all the GPS coordinates of the relays before we can proceed; priority will be given to completing the set up of the relays on Creag Mhaol. No progress this month. **Action: Phil** 

## 8.2 Existing Relays

### 8.2.1 Plockton

We will check the installation and apply a second coat of paint to the school wall. Action: Phil & Mary

#### 8.2.2 Achmore

The Plusnet router will be replaced with something more suitable. No progress this month. Action: Phil

The test the maximum speed that the radio link from Achmore Hall to Creag Mhaol will support the router in Achmore Hall will need to be upgraded. At the moment it has "only" 100 Mbps Ethernet ports and it is expected that the radio link will be able to run well over this speed. However we test the speed from router to router so the 100 Mbps port on the Achmore Hall router would be the limiting factor. We will therefore replace the router with one that can support 1 Gbps Ethernet ports; we have a suitable router "in stock". The corresponding router on Creag Mhaol has already been upgraded. No progress this month. Action: Phil

#### 8.2.3 Lochcarron

Link capacity testing is required. Action: Phil

We will install a Raspberry Pi micro computer to facilitate gateway line speed tests. Action: Phil

8.2.4 Other relays

No issues.

## 8.3 Backbone development

### 8.3.1 New relays

#### 8.3.1.1 Completed

No progress this month.

### 8.3.1.2 Next steps

The new relay automated recovery algorithms are being tested (some rather unexpectedly)

Re-align the existing Portchullin Access Point

Add an additional Portchullin Access Point

The buried mains power cables need to be permanently marked and documented.

Install one subscriber's test equipment in Portchullin

Install backup equipment on Achmore High and Achmore Low relays

## **Action: All**

8.3.2 The Glen

One access point will be upgraded to see if that will reduce the noise levels. No progress this month. Action: Phil

8.3.3 Ardaneaskan East

Nothing to report

8.3.4 Leacanashie

Nothing to report

8.3.5 Portchullin (raised beach)

The Portchullin enclosures and access points will be upgraded. Action: Phil

8.3.6 Craig

We will review the link when other work is complete. Action: Phil

8.3.7 North Strome

Nothing to report

8.3.8 Strome Ferry

Nothing to report

8.3.9 Ardnarff

Nothing to report

8.3.10 Reraig

We have surveyed various locations for a relay to provide an access point for Reraig. Access will almost certainly require a much higher relay than we have built so far. We will return to the relay investigation and build once the current relays are active. **Action: Phil** 

### 8.4 Testing

8.4.1 Management & accounting software

Nothing to report.

## 8.5 Restoring power to the old TV repeater

8.5.1 Removal of old cable

No progress this month.

8.5.2 Protection of cable on the hill

All the cable on the hill has been buried but the routes still need to be marked.

8.5.3 Backup Generator

No progress this month.

8.6 ISPs

No issues

### 8.7 Implementations

8.7.1 Phase 3 - Relays and creation of access points for the remainder of residents and connect trial subscribers.

8.7.1.1 Ardaneaskan East

Equipment has been configured for two more installations which are pending. Action: Phil, Mary & Ken No further installations are waiting to be scheduled.

8.7.1.2 Strome Ferry

We are experiencing some reduction in throughput due to the tides. We are testing alternative equipment to determine the best combinations before commencing the full roll out of installations. **Action: Phil, Neil** 

8.7.1.3 Leacanashie

One installation is waiting to be scheduled. Action: Phil

8.7.1.4 North Strome

Two installations are waiting to be scheduled. Action: Phil

8.7.1.5 *Achmore* 

One installation is waiting to be scheduled. Action: Phil

8.7.1.6 Portchullin

The enclosures at Portchullin have been measured so replacements can be prepared. Action: Phil

- 8.7.2 Phase 4 Further investigations / backbone development required.
- 8.7.2.1 Ardaneaskan West
- 8.7.2.2 Ardnarff
- 8.7.2.3 *Reraig*
- 8.7.2.4 Lochcarron
- 8.7.2.5 Strathcarron
- 8.8 Company Logo

No progress this month. Action: All

8.9 General Data Protection Regulation (Data Protection Act)

Nothing to report this month

# 9 Director's training session

## 9.1 Configuring Ubiquiti and MikroTik equipment

A training session was scheduled to follow the meeting to give everyone access to some of our monitoring software however as the meeting took place by Zoom this will be rescheduled and will be completed at a later date; more will follow in the coming months. Action: All

# 10 Next meeting

Date of next meeting Wednesday 15<sup>th</sup> December 19:30.

The meeting finished at 8:20 pm