

East side There are no features of interest and the lower half is covered by the agricultural building.

North(rear). Roof slate, stone ridge piece with raised copings on east and west ends and kneelers.

There are stressed quoins at east end only.

One window in the upper storey with moulded surround and blocked with a painted window on black background. Lower storey; one window at west end with architrave surround. To the west of this window is a narrow outshut with a stone slab roof and modern window with stone lintel. Below a wider outshut projects north to form a porch and roofed with stone slabs; a small window faces east.

To the west of the porch is a further outshut projecting beyond the porch to the north; this has a stone slab roof and one small window in the upper storey with stressed stone sill; another window below has large stone lintel and narrow stone sill. On the west of the outshut a gable-ended wing appears to have been made by raising the outshut. Red bricks can be seen under the rendering on the west side of the wing while the east side is stone. The roof is of slate with stone ridge piece and raised copings ending in very poor quality kneelers at the east and west ends. A red brick chimney rises out of the west wall of the gable.

There are three windows in the gable end; one small window near the roof, one below towards the east with stone lintel and sill and 3/3 panes; one in the lower storey has large stone lintel and sill.

West side There is an external, stepped chimney stack, with flue entering the wall below the stack. The lower half of the gable is covered by a stone lean-to belonging to the adjoining property.

Interior description

The south door enters into a hall which runs the width of the house. At the south end of the east wall a door enters into the east sitting room.

Features of interest:- 1. Recessed window with shutters.
2. One plaster-covered beam, west of centre.

Returning to the hall a door at the south end of the west wall leads into the dining room. Features of interest:- 1. Fire-place with stone lintel and jambs with modern wooden surround. Over the fire-place is a simple plaster moulding from the mantle-piece to the cornice. The south side at the top has been cut out to accommodate the door. It would appear the original door was north of the fireplace where the wall surface remains uneven.

2. East end of north wall, modern hatch made out of a recessed window.

At the south end of the west wall a door leads into the west sitting room. The east door in this room is hung with 'H' shaped hinges and the door in the west wall has 'L' shaped hinges. Features of interest are:- 1. Chamfered beam running north to south near the east wall.

2. Recessed windows.

3. Wall cupboard south of modern fireplace in west wall.

A staircase previously rose to the upper storey starting along the corner at the north end of the west wall, turning and continuing along the side of the north wall.

Returning to the hall, the north end of the west wall bends in west to east under the stairs where the former entrance to the dining room would have been. The door leading into the modern porch is the original entrance into the house and has old stone convex moulded lintel with jambs built of five separate stones resting on moulded pedestals.

In the west wall of the porch a door leads down one step into a passage. On the south wall, the hatch, a one-time window, has a moulded stone surround. To the north side of the passage at the west end a door leads into the larder and the west end passage door, a recent insertion, leads into the kitchen, up one step. An old stone surround encloses a modern kitchen stove.