

Rodney Stoke Parish Council

Safety Inspection August 2024 – wear hi viz jackets

Assets

Present: Chairman, Clerk

✓

Rodney Stoke

Item	Visual	Push Test	Action
Dog Bin Barrow Wood Lane	✓		
Church noticeboard	✓	✓	
Millway noticeboard	✓	✓	
Millway gritbin	✓	✓	full
Bench (fp33) (off Scaddens)	✓	✓	
Pound plaque & stone	✓	✓	
Pound bench	✓	✓	
Pound gate	✓	✓	
Pound wall	✓	✓	
Pound solar panel	✓		
Pound bus shelter	✓	✓	
Pound Rubbish Bin	✓	✓	
Brangay dog bin	✓		

Draycott

Item	Visual	Push Test	Action
Cross Farm Road Dog bin	✓		
Bus shelter bin	✓	✓	
Bus shelter & bench	✓	✓	
Back Lane grit bin	✓	✓	¾ full
Noticeboard Back Lane	✓	✓	Overgrown – notify Aster
Post Office noticeboard	✓	✓	
Post Office gritbin	✓	✓	Full
Eastville Lane Dog Bin	✓	✓	
Bay Lane grit bin	✓	✓	½ full
Milking Lane Dog Bin	✓	✓	
Westfield Lane Dog Bin	✓	✓	Needs cutting back
Joy Wills bus shelter	✓	✓	Report for cleaning
Dog bin The Batch	✓	✓	
Grit bin The Batch	✓	✓	2/3 full
Village Pump	✓	✓	
Card memorial & railings	✓	✓	Plaque needs attaching, clear weeds?

/

Memorial Hall/Rev Cobley Playing Field

Item	Visual	Push Test	Action/Comments
Gate and posts	✓	✓	
Tree and tree guard	✓	✓	Replace tree
Driveway	✓	✓	
Signage on driveway	✓	✓	
Fence on driveway	✓	✓	
Overflow area	✓	✓	Needs topping
Hall overflow gate and signs1945	✓	✓	
Zip Wire	✓	✓	Paint? Rust needs clearing
Youth shelter & base	✓	✓	Strim grass to tidy
Vandal proof goal posts	✓	✓	
Plinth and plaques	✓	✓	
Sapling and treeguard	✓	✓	
Play area fence	✓	✓	
Play area silver gate Dbl 1966	✓	✓	
Play area yellow gate	✓	✓	Needs painting
Play area information sign on fence	✓	✓	Needs cleaning
Play area bin	✓	✓	
Play area equipment	✓	✓	The multi gym needs a clean and some paint touched up. The swings need painting.
Play area surface	✓	✓	
Benches in play area	✓	✓	
Small gate & dog sign (field - east)	✓	✓	Sign needs 2 zip ties and post needs servicing to repair the automatic closing mechanism.
6 mature trees	✓	✓	
Bench nr pavilion	✓	✓	
Low wooden barrier by bat superhighway	✓	✓	Metal strap needs reattaching
Pavilion bin	✓	✓	
Pavilion signs x 3 (inc cctv)	✓	✓	
Tree to east boundary	✓	✓	
Victorian gates and fence 1 pedestrian, 1 kissing, 1 double, 30ft fence	✓	✓	The pedestrian gate needs servicing and the post needs to be cemented in.
Rev Cobley fence (east boundary)	✓	✓	
A371 fence	✓	✓	
A371 bat superhighway	✓	✓	
Bat boxes	✓	✓	
A371 trees	✓	✓	
A371 hedging	✓	✓	

Low chain marker fence & gate	✓	✓	Ragwort needs strimming off and the grass needs strimming tidying.
Driveway	✓	✓	
CCTV cameras and equipment	✓		

Burial Ground - Independent 6 monthly Inspection Report