

Tree Inspection: Memorial Field

Date of Inspection: 14th January 2024

Present: Cllrs Spooner Vining Parish Clerk H Marshall

Site Conditions: Ground wet. Large open field. All trees accessible. No structures overhung. Low foot fall. Mix of users.

All trees checked for:

- Splits and cracks
- Dead wood
- Crown die back
- Cavities - any increase in size
- Obvious root changes
- Fungi
- height and spread

Risk:


Low = Inspect in 12 Months

Tolerable inspect in 6 months and take action indicated

Serious take action and restrict access.

| Tree | Visual comments | Impacts | Risk | Action |
|--------------|---|---------------|------|--------------------------------------|
| 1 Common Oak | Healthy in bud Remove tree guard in few years | None observed | Low | Identify species Review in 1 year |
| 2 | Metal guard embedded in trunk. Healthy in bud | None observed | Low | Identify species Review in 1 year |
| 3 | Mistletoe present in number of branches. Healthy in bud, | None observed | Low | Identify species Review in 1 year |
| 4 | Some limbs are very low. Healthy growth. | None observed | Low | Identify species Review in 1 year |

Memorial Field Trees Placement



Bench

Access